

The visual inspection of high pressure cylinders is critical to high pressure cylinder safety. The Federal Government (DOT & OSHA) requires visual inspections for all high pressure cylinders -- including SCBA cylinders. SCUBA cylinders must be visually inspected at least yearly while SCBA cylinders have inspection intervals prescribed by both the manufacturer and the Federal Government. OSHA and DOT further require that all employees using, handling or filling such cylinders MUST have appropriate HAZMAT and other function specific training. This training must be administered within within 90 days of hiring and every 3 years thereafter -- and must be documented in individual training records. (Continental Fire can provide this service to your department , please contact us for more information and pricing.

Continental Fire & Safety, Inc. is PSI PCI trained and certified in visual inspection and Eddy Current testing as required by DOT.

Are your cylinders being inspected and tested by a trained and licensed facility? Do they do the work or are they being sent out to someone you don't know? All cylinder inspections and testing are DONE in house located at 2740 Kuser Rd in Hamilton, NJ. You are welcome to stop by during business hours to see for yourself why Continental is the largest cylinder Re-Qualifier in New Jersey.